



Repairing Holes

"Outside"




We frequently want to repair holes,
- Move a chartplotter
- Move Gauges, Controls,
Transducers

"Outside"




Grind to Knife (Chisel)
Edge from Inside

"Outside"



Install backer board "Outside"
Can be Formica Plywood,
PVC Board, Waxed Ply, Foil Tape
Etc.
Using Tape, Hotglue, Screws...

"Outside"



Layer Inside:

- Gelcoat (If Desired)
- Mat
- More Glass (Structure)
- Core (Maybe)
- Glass on top of Core (Maybe)

Finish "Outside" as desired:
Paint, Gelcoat, Etc.

Technical Questions: support@usfiberglasssupply.com
352-377-4146

Online: www.usfiberglasssupply.com
3001 NE 20th Way Gainesville FL 32609